# **Red Cedar Professional Inspections**



# April 28th 2023, 11:00 am

Inspection performed by: Blain King (TN #2750) (615) 988-0678

blain@redcedarinspections.com

### **General Information**

BUILDING ADDRESS: XXX Josie Ln

CITY: Clarksville

STATE: TN

**ZIP CODE**: 37043

**INSPECTION DESCRIPTION:** 

**SQUARE FOOTAGE**: 2500

Picture:



Has the PRE-INSPECTION AGREEMENT been signed by the client?

Yes

Is the client present for the inspection?

Yes

Is the real estate agent present for the inspection?

No

# **EXTERNAL AMENITIES**

# SHED / OUTBUILDINGS Satisfactory

Notes:

Shed was locked the time of inspection. Small damaged section of siding lower right hand corner of front. Recommend evaluation by a qualified contractor.







POOL N/A

Notes:

## **ROOF**

**ROOF TYPE** Gable

Notes:

**ROOF MATERIAL** Asphalt Shingles

Notes:

SHINGLES MISSING / DAMAGED? Satisfactory

Notes:

**ROOF INSTALLATION** Satisfactory

Notes:

**FLASHING** Satisfactory

Notes:

**GUTTERS AND DRAINAGE** Fair

Splash blocks within 5 ft of house. Loose downspout noted Southeast corner of house. Gutter it front drains on the sidewalk presenting slip hazard in freezing weather. Recommend evaluation by qualified contractor.











**SKYLIGHTS / ROOF PENETRATIONS** Satisfactory

Notes:

MILDEW PRESENT ON ROOF? No

Notes:

# **EXTERIOR**

**SIDING MATERIAL** Vinyl

Notes:

**SIDING CONDITION** Fair

Several loose pieces of siding noted at the bottom of Southside wall. Distorted citing noted side of fireplace exterior. Green moss noted on north side wall. Recommend evaluation by qualified contractor. Recommend cleaning by qualified contractor.







**FLASHING** Satisfactory

Notes:

**EAVES** Satisfactory

Notes:

FASCIA Satisfactory

Notes:

**SOFFITS** Satisfactory

Notes:

TRIM Satisfactory

Notes:

**EXTERIOR DOORS** Satisfactory





**PATIO** Satisfactory

Notes:



**STEPS** Satisfactory Notes:



# **LANDSCAPE**

**VEGETATION** Satisfactory

Notes:

**GRADING** Satisfactory

Notes:

**SURFACE DRAINAGE** Satisfactory

**RETAINING WALL** N/A

Notes:

WALKWAYS Satisfactory

Notes:

# **GARAGE**

**DRIVEWAY** Satisfactory

Notes:

Small amount of spalling noted. Small cracks noted. Recommend owner continue to monitor.







**GARAGE DOOR** Satisfactory Notes:



GARAGE DOOR OPENER Satisfactory

Obstruction and IR test performed. Both safety features operate as intended at time of inspection.





# **ATTIC**

**ROOF SHEATHING** Satisfactory

Notes:









FRAMEWORK Satisfactory

Notes:

**VENTILATION** Satisfactory



**INSULATION** Satisfactory Notes:



**ACCESS** Satisfactory Notes:



CHIMNEY AREA N/A
Notes:
BATHROOM 1
DOORS Satisfactory
Notes:



**FLOORING** Satisfactory Notes:





WALLS Fair

Missing baseboard trim noted between shower and master bath closet. Moisture meter reads 4.6%. No active sign of leaking at time of inspection. Recommend evaluation and repair by qualified contractor.







**WINDOWS** Satisfactory Notes: Stationary frosted glass.



**CEILING** Satisfactory Notes:



**COUNTERS** Satisfactory Notes:



**SINKS** Fair

Notes:

Right side sink plug does not seal properly. Recommend evaluation by qualified contractor.



BATHTUB / SHOWER S

Satisfactory











**TOILET** Satisfactory Notes:



**OUTLETS** Satisfactory Notes:



**LIGHTING** Satisfactory Notes:



**VENTING** Satisfactory Notes:

# **BATHROOM 2**

**DOORS** Satisfactory Notes:



**FLOORING** Satisfactory Notes:





**WALLS** Satisfactory Notes:



**CEILING** Satisfactory Notes:



**COUNTERS** Satisfactory Notes:



**SINKS** Satisfactory

BATHTUB / SHOWER Satisfactory



**TOILET** Satisfactory Notes:





**OUTLETS** Satisfactory

GFCI trip successful. However, GFCI is not located in the bathroom. This outlet is fed from GFCI in master bath.



**LIGHTING** Satisfactory Notes:



**VENTING** Poor

### Notes:

Bathroom 2 (upper level) vent appears to be exiting at soffit. However, inspector was unable to verify end of vent. Recommend evaluation by qualified contractor.



**BATHROOM 3** 

**DOORS** Satisfactory Notes:



**FLOORING** Satisfactory Notes:



WALLS Satisfactory





**CEILING** Satisfactory Notes:



**SINKS** Satisfactory Notes:



**TOILET** Satisfactory Notes:



**OUTLETS** Fair

Outlet in powder room is loose in wall. Recommend evaluation by qualified contractor.



**LIGHTING** Satisfactory



**VENTING** Satisfactory Notes:

# **BATHROOM 4**

DOORS N/A

Notes:

# **BEDROOM 1**

**DOORS** Satisfactory



**FLOORING** Satisfactory





**WALLS** Satisfactory Notes:



**WINDOWS** Satisfactory Notes:





**CEILINGS** Satisfactory Notes:





**CLOSETS** Satisfactory

Walk-in closet and master bath. Built-in closet on West wall.



**OUTLETS** Satisfactory Notes:





**LIGHTING** Satisfactory

Notes:

**CEILING FANS** Satisfactory

Notes:



# **BEDROOM 2**

**DOORS** Satisfactory



**FLOORING** Satisfactory Notes:



**WALLS** Satisfactory Notes:



**WINDOWS** Satisfactory Notes:



**CEILINGS** Satisfactory Notes:



**CLOSETS** Satisfactory Notes:



**OUTLETS** Satisfactory Notes:



**LIGHTING** Satisfactory

Notes:

**CEILING FANS** Satisfactory

Notes:



# **BEDROOM 3**

**DOORS** Fair

Notes:

Scratches noted on bottom of bedroom number three door. Recommend evaluation by a qualified contractor.







**FLOORING** Satisfactory
Notes:
Bedroom three carpet is obstructed by an area rug.



WALLS Satisfactory



**WINDOWS** Satisfactory Notes:





**CEILINGS** Satisfactory Notes:



**CLOSETS** Satisfactory

Bedroom three closet door has a small dent in top left hand corner. Recommend evaluation by qualified contractor.



**OUTLETS** Satisfactory Notes:





**LIGHTING** Satisfactory

Notes:

**CEILING FANS** Satisfactory



BEDROOM 4

DOORS Satisfactory

Notes:



**FLOORING** Satisfactory Notes:





WALLS Satisfactory

Hole in wall at baseboard to left of closet door. Hooks and holes noted on multiple walls. Recommend evaluation by qualified contractor.







**WINDOWS** Fair Notes:



**CEILINGS** Satisfactory Notes:



**CLOSETS** Satisfactory Notes:



**OUTLETS** Satisfactory Notes:



**LIGHTING** Satisfactory

**CEILING FANS** Satisfactory



**BEDROOM 5** 

**DOORS** Satisfactory

Notes:





**FLOORING** Satisfactory

Notes:

Flooring was obstructed by multiple items during inspection.



WALLS Satisfactory



**WINDOWS** Satisfactory Notes:



**CEILINGS** Satisfactory Notes:



**CLOSETS** Satisfactory Notes:



**OUTLETS** Satisfactory Notes:



**LIGHTING** Satisfactory

Notes:

**CEILING FANS** Satisfactory



# **BEDROOM 6**

DOORS N/A

Notes:

**LIVING AREA 1** 

**DOORS** Satisfactory



**FLOORING** Satisfactory Notes:





**STAIRWAYS** Satisfactory Notes:






**WALLS** Satisfactory Notes:





**WINDOWS** Fair











**CEILING** Satisfactory Notes:



**OUTLETS** Satisfactory





**LIGHTING** Satisfactory

Notes:

**CEILING FANS** Satisfactory

Notes:



FIREPLACE Poor

Notes:

Gas shut off valve located inside of firebox. Recommend evaluation by a qualified fireplace contractor.





LIVING AREA 2

DOORS N/A

# **KITCHEN**

**FLOORING** Satisfactory



**WALLS** Satisfactory Notes:





**WINDOWS** Satisfactory Notes:





**CEILING** Satisfactory Notes:



**COUNTERTOPS** Satisfactory Notes:



**CABINETS** Satisfactory Notes:









**PANTRY** Satisfactory Notes:





**SINK / GARBAGE DISPOSAL** Satisfactory Notes:

Limited ability to inspect under sink due to storage of cleaning supplies.







**DISHWASHER** Satisfactory Notes:





**STOVE / OVEN** Satisfactory Notes:













**EXHAUST HOOD** N/A

Microwave fan exhaust hood. Hood exhausts above microwave.

**REFRIGERATOR** Satisfactory







**OUTLETS** Satisfactory Notes:



**DINING ROOM**FLOORING Satisfactory
Notes:



**WALLS** Satisfactory Notes:





WINDOWS Fair

Left side of window frame on bottom left is damaged. Possible chew marks from pet. Seal is damaged. Recommend evaluation by qualified contractor.







**CEILING** Satisfactory Notes:



**OUTLETS** Satisfactory Notes:



**LIGHTING** Satisfactory Notes:



LAUNDRY ROOM
OUTLETS Satisfactory
Notes:



**WATER SUPPLY** Satisfactory Notes:



**DRAINAGE** Satisfactory Notes:



**VENTILATION** Satisfactory Notes:



FOUNDATION
FOUNDATION MATERIAL Masonry
Notes:
Masonry foundation with brick fascia.



**SLAB** Not Inspected

Slabing garage is covered with vinyl flooring.



**WALLS** Satisfactory

Notes:

Crack noted in Southeast corner of garage masonry wall. No corresponding crack on outside brick fascia. Recommend owner continue to monitor.



**DRAINAGE** Satisfactory

Notes:

**VENTILATION** Satisfactory

Notes:

**OUTLETS** Satisfactory



MILDEW PRESENT AT FOUNDATION? No

Notes:

## **PLUMBING**

WATER SUPPLY PRESSURE Satisfactory

Notes:



WATER SUPPLY PIPING SIZE Satisfactory

Notes:

MAIN SHUTOFF VALVE Satisfactory

Notes:

Main shut off and regulator located on North wall inside garage.



SINK / TOILET SHUTOFF VALVES Satisfactory

PRESSURE AT FAUCETS Satisfactory

Notes:

**DRAINAGE** Satisfactory

Notes:

**SEWER / SEPTIC** Satisfactory

Notes:

WATER HEATER Satisfactory

Notes:





**VENT SYSTEM** Satisfactory

Notes:

**ELECTRICAL** 

SERVICE DROP / LATERAL Satisfactory



**CONDUCTORS** Satisfactory

## **OVERCURRENT PROTECTION** Satisfactory

Notes:

Extra 14ga and 12 ga NM sheath cables present in panel marked crawlspace. These cables do not appear to be energized.



**RECEPTACLES** Satisfactory

Notes:

AMP RATING 200 Amps

Notes:

MAIN DISCONNECT Satisfactory

Notes:



WIRING METHOD Non-Metallic Sheathed Cable

Notes:

**CIRCUIT PANEL** Satisfactory



# **HEATING & COOLING**

**ENERGY SOURCE** Electric

Notes:

**HEATING SYSTEM** Forced Air

Notes:

Heat pump not tested in heat mode due to outside temp >60°F.





**HEATING SYSTEM OPERATION** Satisfactory

Notes:

**DUCTWORK / PIPING** Satisfactory

Notes:

**COOLING SYSTEM** Satisfactory

Notes:

**COOLING SYSTEM OPERATION** Fair

Notes:

Delta T on upstairs unit noted to be  $10^\circ$  f. Recommend evaluation by qualified contractor.









**THERMOSTAT** Satisfactory Notes:





AIR FILTER(S) Satisfactory

Notes:

**SMOKE ALARM(S)** Satisfactory

Notes:

Smoke alarms noted in every sleeping area and in every hallway. Smoke alarms noted in laundry room. Smoke alarm missing in garage. Recommend replacement by qualified handyman.

CARBON MONOXIDE ALARM(S) Satisfactory

Notes:

Carbon monoxide monitors located outside sleeping areas.

## **ADDITIONAL DETAILS**

### **SUMMARY:**

### **Roof - Gutters and Drainage**

Splash blocks within 5 ft of house. Loose downspout noted Southeast corner of house. Gutter it front drains on the sidewalk presenting slip hazard in freezing weather. Recommend evaluation by qualified contractor.

## **Exterior - Siding Condition**

Several loose pieces of siding noted at the bottom of Southside wall. Distorted citing noted side of fireplace exterior. Green moss noted on north side wall. Recommend evaluation by qualified contractor. Recommend cleaning by qualified contractor.

## **Bathroom 2 - Venting**

Bathroom 2 (upper level) vent appears to be exiting at soffit. However, inspector was unable to verify end of vent. Recommend evaluation by qualified contractor.

#### **Bathroom 3 - Outlets**

Outlet in powder room is loose in wall. Recommend evaluation by qualified contractor.

#### **Bedroom 4 - Windows**

## **Living Area 1 - Windows**

Window above entryway displays signs of seal failure. Recommend evaluation by qualified contractor.

# **Dining Room - Windows**

Left side of window frame on bottom left is damaged. Possible chew marks from pet. Seal is damaged. Recommend evaluation by qualified contractor.

## **Heating & Cooling - Cooling System Operation**

Delta T on upstairs unit noted to be 10° f. Recommend evaluation by qualified contractor.

# **Heating & Cooling - Smoke Alarm(s)**

Smoke alarms noted in every sleeping area and in every hallway. Smoke alarms noted in laundry room. Smoke alarm missing in garage. Recommend replacement by qualified handyman.